

### **Kartlegging av sprekken i Preikestolen**

Determination of the crack at Preikestolen

Preikestolen (The Pulpit Rock) has a long crack that is several meters deep.

The fear of creating a floodwave by a falling rock is great. The mountain is monitored by laser scanning and 3D modeling as well as by pressure measurement of the rock. All data are placed into a chart to check any increment. The researchers do not believe that the pulpit has moved lately and they do not think there is any immediate danger in the area.